

BUILDING INSPECTOR/HEALTH OFFICER'S REPORT (Cont'd)
January 2, 2016 through December 31, 2016

| | | |
|--|-------------------------|----------------------------|
| Single Family | 76 | \$21,879,675 |
| Raze (demolition) | 2 | \$0 |
| Foundation | 1 | \$9,000 |
| Multi-Family | 2 (12 Units) | \$2,341,736 |
| Two Family | 2 (4 Units) | \$717,562 |
| Accessory Living Units | 9 | \$394,596 |
| Mobile Homes/Manufactured Homes | 8 | \$365,080 |
| Demolition | 7 | \$0 |
| Additions & Alterations | 219 (70 Solar Projects) | \$4,035,716 |
| Accessory Structures | 65 | \$731,755 |
| Pools | 34 | \$549,384 |
| Fill In/Demo | 2 | \$0 |
| Industrial/Commercial | 9 | \$64,519,577 |
| Foundation | 1 | \$425,000 |
| Demolition | 2 | \$0 |
| Additions/Alterations | 61 | \$3,182,971 |
| Signs | 27 | \$184,139 |
| Temporary Signs | 27 | \$0 |
| <u>TOTAL</u> | <u>554</u> | <u>\$99,336,191</u> |

BUILDING INSPECTOR/HEALTH OFFICER'S REPORT (Cont'd)

~~January 1, 2016 through December 31, 2016

ADDITIONAL PERMITS ISSUED

| | |
|----------------------------------|--------------|
| Electrical | 518 |
| Plumbing | 159 |
| Septic | 50 |
| Septic Plan Reviews | 83 |
| Well | 37 |
| Fireplace/Woodstove/Pellet stove | 24 |
| Driveway | 44 |
| Vendors/Secondhand | 24 |
| <u>Mechanical</u> | <u>716</u> |
| TOTAL: | 1,655 |

TOTAL PERMITS & PLAN REVIEWS **2,209**

CERTIFICATES OF OCCUPANCY

Residential - 199

(87 Single Family Dwellings, 4 Accessory Living Units, 4 Mobile Home, 101 Other)

Commercial - 41

(13 New Construction & Additions, 28 Other)

BUILDING DIVISION REVENUES

TOTAL FEES COLLECTED

\$670,503

BUILDING INSPECTOR/HEALTH OFFICER'S REPORT (Cont'd)

Inspections

~~January 1, 2016 through December 31, 2016

| | |
|------------------------|-----------------------|
| FINAL | 351 |
| FRAME | 310 |
| ELECTRICAL | 806 |
| PLUMBING | 333 |
| INSULATION | 199 |
| FOUNDATION | 236 |
| SEPTIC | 140 |
| MECHANICAL | 1271 |
| WOODSTOVE/PELLET STOVE | 26 |
| OTHER | 268 |
| <i>TOTAL</i> | <i>3,940**</i> |

**This number indicates scheduled inspections performed and may not represent the complete total number of inspections conducted that may not have been scheduled.